




# Corrosion Phased Array Report

<b>Plant:</b>	
<b>Project:</b>	By Pass LP KOD
<b>Equipment No.:</b>	
<b>Description:</b>	
<b>Inspection Date:</b>	91.02.15~16
<b>Location:</b>	Bottom Dish End



⇒ There were 3 critical points in inspected area to be calculated FFS.

Inspector(s):	Approve by:	Client:
Level: II	Level: III	
Report date: 91.05.01	Date: 91.05.01	